



REPUBLIKA NG PILIPINAS
KAGAWARAN NG KALUSUGAN
PANLABAS NA PAGPAPAGANAP
PAMPUROK TANGGAPANG PANGKALUSUGAN BLG. 6
WESTERN VISAYAS MEDICAL CENTER
PROCUREMENT SECTION
Q. ABETO ST., MANDURRIO, ILOILO CITY

June 08, 2019

INVITATION FOR PRICE QUOTATION

You are hereby invited to quote your prices on the articles listed below. Please submit your quotation in sealed envelope to the **BAC Office** of the Western Visayas Medical Center, Iloilo City or through the bearer **on or before June 13, 2019 at 09:00 AM**.

Please secure the canvass form at the Procurement Office.

PR #	QTY	UNIT	LIST OF ARTICLES FOR SHOPPING	UNIT COST	END – USER MODE OF PROC	TIMES POSTED
SERVICES						
19-03-0225	1	LOT	Siphoning of Septic Tank with A = 4mx2mx150cm Location: St. Padre Pio Ward / Cathlab	30,000.00	HEMU Small Value	4
19-03-0227	1	LOT	Repair, Supply and Installation of (1) unit Motor Pump, 5HP capacity w/ SN: WO-10573-1004-47; Model: 3656; Baldor/Gould Brand Location: Guard House Pump Station Scope of Work: Rewind the field coil 2. To replace the defective parts bearing 6204 abd 6203 double seal 3. Mechanical Seal	15,000.00	HEMU Small Value	4
19-03-0215	1	LOT	Labor and Materials for Pull-out and Transfer of Installation of 2 units Aircon Intended for the Server Rm. (relocation) of two (2) Units Hi wall Aircon Unit Location: CIMU Server Rm. Php. 9,100/unit	18,200.00	HEMU Small Value	4
19-03-0227	1	LOT	Repair, Supply and Installation of (1) Unit Motor Pump, 5HP Capacity w. SN: WO-10573-1004-47; Model: 3656; Baldor/Gould Brand Location: Guard House Pump Station Scope of Work: 1. Rewind the field coil 2. To replace the defective parts bearing 6204 and 6203 double seal 3. Mechanical Seal		HEMU Small Value	2
19-05-0363	1	LOT	Supply, Repair of 1 unit Service Vehicle w Plate No. SFD-421, Mitsubishi Brand (Please see attached pre-repair inspection report)	50,000.00	HEMU Small Value	2
19-05-0357	1	LOT	Supply, Install and Calibration of Automatic Voltage Regulator for Cummins Brand Gen. Set, 488KVA /500KVA Note: One (1) Year Warrany After-Sales/Installation	48,000.00	HEMU Small Value	2
19-05-0351	1	LOT	Repair, Supply and Restoration the Operation	25,000.00	HEMU	2


Capacity of Aircondition of Ambulance with Plate No.

/Small Value

SAA-2549, Model: View; Brand: Foton

Scope of Work:

1. To check the Operational capacity of Aircon evaporator
2. Reflushing condenser and recharging of freon to its operational capacity
3. General cleaning and leak testing (front/back control air duct)
4. Functionality test



GILLEE A. MEDROCILLO, RRT
SAO/Procurement Officer

For Bids and Awards Committee:



MA. VIOLETA C. CALOPEZ, RN, MAN
Chairman, Bids and Awards Committee - Services